

Wear Debris Analysis Handbook  
Approximately 140 pages  
by Trevor Hunt  
Hardback £35 / \$60 plus £3 / \$5 post & packing (this figure remains the same whether one book or more are ordered)  
Publication date: March 1999  
ISBN: 1 901892 02 6  
Sold with a 28 day money back guarantee (assuming it is returned to the publisher in the same condition it was sent out)

An ideal - and affordable - text for engineers and maintenance professional with an interest in wear debris analysis. This title does not attempt to baffle with the technology, but introduces it at an understandable level, touching on the basic theory and concepts, available equipment and practical issues relevant to the engineer as well as highlighting several case studies with which the reader can relate.

Other books in this twelve title series focus on thermography, vibration, corrosion, noise, ultrasonics and oil analysis.

#### Chapter One

##### INTRODUCTION TO WEAR DEBRIS ANALYSIS

- 1.1 Introduction
- 1.2 Overall view of methods
  - 1.2.1 Choice
  - 1.2.2 Type of connection
  - 1.2.3 Type of preparation
  - 1.2.4 Type of analysis
- 1.3 Scope

#### Chapter Two

##### BASIC CONCEPTS AND THEORY

- 2.1 Quantity and size
  - 2.1.1 Trend analysis
  - 2.1.2 Absolute levels
- 2.2 Visual identification – Shape
  - 2.2.1 Systematic particle analysis
  - 2.2.2 Wear and wear particles
  - 2.2.3 Wear particle atlas (WPA)
  - 2.2.4 Computer-Aided Systematic Particle Analysis (CASPA)
  - 2.2.5 Computer-Aided Vision Engineering (CAVE)
- 2.3 Composition
  - 2.3.1 Origins
  - 2.3.2 Spectrometric identification

#### Chapter Three

##### PRACTICAL ISSUES

- 3.1 Sampling
  - 3.1.1 Position
  - 3.1.2 Preparation
  - 3.1.3 Time
  - 3.1.4 Grease
- 3.2 Analysis
  - 3.2.1 In-line and on-line analysis
  - 3.2.2 Off-line analysis
- 3.3 Reporting

#### Chapter Four

##### EQUIPMENT AND INSTRUMENTATION

- 4.1 Sample points and probes
  - 4.1.1 Sample points
  - 4.1.2 Sample probe

- 4.2 Samplers
- 4.3 Patch making
  - 4.3.1 On-line Compar
  - 4.3.2 Off-line Millipore
- 4.4 Patch analysers, including image analysis
  - 4.4.1 Comparative analysis
  - 4.4.2 Automatic analysis
  - 4.4.3 Image analysis
- 4.5 Wear debris atlases
- 4.6 Off-line debris detectors, including Ferrography
  - 4.6.1 Ferrous debris
  - 4.6.2 All metal debris
  - 4.6.3 All debris
- 4.7 Off-line particle analysers, including counters
  - 4.7.1 Optical
  - 4.7.2 Acoustic spectroscopy
- 4.8 In-line debris detectors
  - 4.8.1 Magnetic/conductance
  - 4.8.2 Magnetic/inductance
  - 4.8.3 Thin film wear and radioactivation
  - 4.8.4 Mesh/conductance
- 4.9 In-line particle analysers, including counters
  - 4.9.1 Inductance
  - 4.9.2 Ultrasonics
- 4.10 On-line debris detectors
  - 4.10.1 Electrical conductance
  - 4.10.2 Magnetic attraction
  - 4.10.3 Optical time of transition
  - 4.10.4 Thin film wear
- 4.11 On-line particle analysers, including counters
  - 4.11.1 Filter blockage
  - 4.11.2 Inductance
  - 4.11.3 Optical obscuration
  - 4.11.4 Ultrasonics
- 4.12 Spectrometry
- 4.13 Kits

#### Chapter Five

##### APPLICATIONS AND CASE STUDIES

- 5.1 Applications
  - 5.1.1 General comments
  - 5.1.2 Appropriate systems and machinery
    - 5.1.3 Why wear debris analysis is so successful
- 5.2 Case studies
  - 5.2.1 Experimental testing
    - a. Individual tests
      - In-line metal detection using the ODM
    - b. Comparative tests
      - Loaded bearing rig using vibration, temperature, spectroscopy, ultrasonics and WDA
  - 5.2.2 Industrial use
    - a. Individual tests
      - Marine gear box using the MPD
      - British Rail rolling stock using spectroscopy
      - 1000 tonne press using the CSI OilView®
      - Hydraulic robot using filter blockage
      - Marine diesel engines using Ferrography
    - b. Comparative tests
      - Coal mill gearboxes using vibration, oil analysis and WDA
      - Gear drive of a cement plant mill using vibration and WDA (RPD)

#### Chapter Six

##### BUYERS' GUIDE

- 6.1 Companies (including oil analysis)

- 6.2 Equipment & Instrumentation
- 6.3 Services, Laboratories, Consultants & Training

- 7.3 References
- 7.4 Bibliography (not referred to in the book)

- Chapter Seven
- REFERENCE
- 7.1 Glossary of terms
  - 7.2 Tables
  - 7.2.1 Compatibility of membrane filters with liquids

- Chapter Eight
- INDEX SECTION
- EDITORIAL INDEX
- INDEX OF Authors

**ORDER FORM**

**Fax to: (Int'l) +44-1451-870661**  
**(UK) 01451-870661**

I would like to order ..... copies of the  
 Wear Debris Analysis Handbook by Trevor  
 Hunt.

**Total price @ £35 / US\$60 per copy plus  
 £3 / US\$7 per order:**

**Payment by Credit Card**

**Card Type (please circle) :**

American Express    VISA    Mastercard

**Card Number:**

**Expiry Date:**

**Cardholder's Name:**

**Address where card is registered:**

Address: .....

.....

Post/Zip Code: .....

Country .....

E-mail: .....

Tel: .....

Fax: .....

.....

**Delivery Details (if different from above)**

Name: .....

Company: .....

Address: .....

.....

.....

Post/Zip Code: .....

Country: .....